

RECEIVED DHSS Breath Alcohol Program
By Carol Day at 12:27 pm, Aug 28, 2009

Complete this report in duplicate at the time of the regular is repaired. Send copy to Department of Health; retain original		nance chec	k, and whenever instrument
DATAMASTER SN		DA	TE OF INSPECTION
204101 LOCATION OF INSTRUMENT (STREET AND CITY)		713	08-23-09 E OF INSPECTION
PUTIMADY COUNTY SHERIFF'S DFFICE	£2	1 IV	0938
CHECKLIST: Place a check (<) to the left of each item if four in observed values where determined.) Unchecked items must	ind to be satisfactory or if o	perating with	
DIAGNOSTIC CHECK (PRINTOUT ATTACHED)	3		
☐ COMPUTER	DETECTOR		
☑ PROGRAM	FILTERS		
HEATERS SAMPLE CHAMBER 49 °C	Quartz standar	D	
FLOW DETECTOR	CALIBRATION		
PUMP HIGH SPEED	PRINTER		
☑ INDICATOR LIGHTS			
☐ TIME AND DATE 0738 08-23-09			,
SIMULATOR TEMPERATURE (34 °C ± 0.2°C) 34,0°	6		
☑ CALIBRATION CHECK -			
Run three tests using a standard solution. All three test			
spread of .005 or less. Check the box corresponding to RECIRCULATION PUMP)	the standard solution being	used. (PRII	NTOUT ATTACHED) (USE
型 0.100% STANDARD - MUST READ BETWEEN 0.095%	and 0 105% INCLUSIVE		
0.040% STANDARD - MUST READ BETWEEN 0.038%			
(ONLY ONE STANDARD IS TO BE USED PER MAINTEN	ANCE REPORT)		
TEST 1 F (098) TEST 2 F	.099	TEST 3	./00
PERFORM R.F.I. TEST (PRINTOUT ATTACHED)			
NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF BREATH TESTS IN EACH RANGE AS FOLLOWS: (DO NOT INCLUDE SIMULATOR TESTS)			
REFUSALS / (004) & (.0509) &	(.1014)	i19) ∂	(Over .19)
List any new parts and describe any alteration or modificatio	n that was made to restore	the instrum	ent to operate satisfactorily
and within established limits (use other side if necessary)	DIVER OF MAIN	#1100	
GUTH REPCO SIMULATOR MODEL	3402C - SERME	117.5	
EXP. 10:15:09			
,100% YRPOR			
INSTRUMENT IS OPERATING WITHIN	'NHSS SPECIFIC	ATION.	Ś
INSPECTING OFFICER SIGNATURE	PRINT NAME	,	
►COP. B. S. Ream	CP4. B. D. RE	903	
TYPE II PERMIT NUMBER/EXPIRATION DATE	TELEPHONE NUMBER		
820065 02 25 10	(lelea) 385-213	<u> </u>	



CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 08340 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography and found to contain 0.1211 percent (w/vol) ethyl alcohol. The expiration date for this lot number is October 15, 2009 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcoholanalysis instrument reading of 0.10 percent BAC.

The alcoho and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

Missigner Staff Wildelman Parlied.

MT INTERESTED TERMINE CHAPATAL CRASS (M. CHAPA)

YESTAHO DEFALSO: MEMBERAD

SEFICER 1. b. : Sec.

PERFIT NUMBERS WEREST

Exhibertion bases becase a

MISTELLAMEURE BROKE

THE STREET SURFACE OF THE

BUMBE (ES)	. 536559	ereja staj
THIERIAL STRUMED	WERTH HER	eds d's
EXTENSE: STRUMEN	. 88.37	Creating ()
期刊 (E27	, ERNE	(99) aq.
ENTERONE STORMAND	a Maria	超进 46.
基.到 4. 700.4	$A_{ij}(n_{ij})$	process.
CATEMPE STAFFORMS	. 160	673 e 47
ELEMENT TAXES	(31)33	W125 417

|₁|| 1₂|| 1₃|| 1₃||

Face This Side Down - This Edge In First

BAC DataMasterEvidence Ticket

MISSOURI STATE HIGHWAY PATROL

BAC TATAMASTER SERTAL HUMBER 20410)

8x08 23/09

B15 9:3

-- DIAGNOSTIC CHECK ---

COMPUTERS OKHY PROGRAM (04-07-2009): UKHY HEATERS SAMPLE CHAMBER: 490 FLOW BETECTORS : ONCEY HIGH SPEED: OKAT DETECTORS CHORY FILTERSI OKPY QUARTE STANDARDA OKAY

FRINTSK TEST

UKRY

!"#*%% (O**, -./0123456789*;< > ?@NBCDEF6
HIJKLMMOPGRSTUVWXYZ[\]^__\abcdefgnijklmno
pqrstovwxgz(I)*"

Operator Signature

Printed on recycled paper with agri-based ink

CHLIBRATIZUNG

CMSU 2208

Printed on recycled paper with agri-based inks

CMSU 2208-0

Face This Side Down - This Edge In First

BAC DataMaster Evidence Ticket

MISSOURI SIMIE HIGHWAY HITWIC

OAC IBTAMAS (EK SEKTAL PURBER CSRIE): UGZZSZÓS

HARCES TIMES COSMO
SUBJECT FREEDS

NOR SINGLE MONTHSON SCHOOL
STRICT DOOR PROPERTY
REFINATION OFFICERS
REFINATION DEFICERS
REFINATION DRIES SENDED
EXPLRATION DRIES SENDED
MISCELLAMEOUS DATAS

--- DREATH ANALYSIS --

RADIO INTERFERENCE

Operator Signature

Printed on recycled paper with agri-based inks

CMSU 2208-0

State of Missouri DEPARTMENT OF HEALTH



TYPE II



BRADLEY REAM

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

02/25/08	Time C. Oolant		
Number 820065	Director of State Public Hastin Laboratory		
Expires 02/25/2010	Director, Department of Health		
MO 500 0774 (7.00)	I.ab. 4 (B7-88)		

MO 580-0771 (7-88)